Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

Cast Column, Market Hall

We were approached by the developers of a derelict Grade II listed building requiring our services for the repair of a cast iron column which had a large hole and crack through part of it, compromising its strength.

The column was repaired by way of a new section of cast iron tubing measuring 2.2m long being cast, before our engineers then went down to site in Plymouth where the new cast section was inset into the original column and stitched in at the top and bottom joints. All stitching repairs were then ground up to the correct profile to match existing shape.

The redevelopment of Market Hall, Devonport, will transform the building into a cutting edge space for digital skills, research, learning and entertain-

ment.

For any Architectural Restorations, please call us for a survey/ quotation.



- On Site Inspection/Quotation
- Metal Stitching Procedures
- Full Crack Detection
- Recasting if needed
- Painting as Required
- 2 Year Guarantee

Breathing new life into damaged cast iron components

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: + 44 (0) 1530 274646

Email: info@slinden.co.uk