



Slinden Services Ltd

Cast Iron Welding and Engineering

MAK 601



A MAK 601 Cylinder Head was received at our works - very badly burnt and cracked in the valve cage pocket.

This area was ground back to sound material and followed by our approved Fusion Welding Procedure.

The repaired area was then NDT inspected to ensure a sound repair had been undertaken then machined back to correct tolerances, spare parts were fitted, followed by thorough cleaning and painting ready for dispatch

The head was witnessed under pressure test by Lloyds for certification purposes prior to dispatch.

Slinden Services Ltd have repaired & reconditioned many different types of MAK Cylinder Heads from the MAK 453, M32 to the MAK 601.

For any Marine Cylinder head repair contact us for a free survey/quotation.

- Full Pressure Testing
- Full Crack Detection
- Fixed Cost Repairs
- Lloyds Welding Procedures
- Machining Facilities
- Fitting Of Spares
- Classification Certificates
- 12 Months Guarantee



*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: 00 44 (0) 1530 274646 Fax: 00 44 (0) 1530 274647 Email: info@slinden.co.uk