



# Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

## Cast Iron Fireplace



This fireplace was brought into our workshop by a building contractor carrying out restorations and refurbishments to a country estate property.

*"I know it is only a small job, but it is urgent, and important to the estate to preserve the original fabric".*



There were four areas to concentrate on repairs: the top flue plate, the hearth base, fire grate, and the side 'cheeks' all required fusion welding repairs by way of our Lloyds approved procedures for cast iron, and the front grill needed

re-welding of previously repaired areas, before crack testing and bead blasting of all welded parts.



It was necessary to remove, drill and tap many old fixing points and allow for new fixing and bolting points, then build up the whole structure to check alignment and fitment, prior to collection and the final phase of black leading of the fireplace once back in situ.



For any Architectural Restorations, please call us for a survey/quotation.



- Lloyds Welding Procedures
- Full Crack Detection
- Full Shot Blasting
- Recasting if needed
- Painting as Required
- 2 Year Guarantee

*Breathing new life into  
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646

Email: [info@slinden.co.uk](mailto:info@slinden.co.uk)