



Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

Cherub Water Feature



- On Site Inspection
- Lloyds Welding Procedures
- ASME IX Welding Codes
- Full Shot Blasting
- Painting As Required
- Recasting Service
- 2 Year Guarantee

A Cheshire hotel contacted us regarding their well-loved water feature which was looking a little “worse for wear” asking if we could undertake a full refurbishment.

We carried out an on site inspection, before dismantling the water feature and bringing all the components back to our Derbyshire workshop.

These components were all shot blasted before welding repairs following our Fusion Welding Procedure.

We had to manufacture new fixing points and water pipe for the head and top bowl as they were missing. The Cherub’s arm had been missing for some time but was not considered a detriment - as you can see from the final photographs!

Following final inspection and shot blasting, we applied a red oxide primer, undercoat and top coat of Brunswick Green, before our engineers reinstalled the feature back in the

Hotel’s grounds, and, as the last photograph shows, back to full working order for future guests to enjoy!

For any Architectural Restorations, please call us for a survey/quotation.



*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646 Fax: +44 (0) 1530 274647 Email: info@slinden.co.uk