


Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

Industrial Toggle Press



An independent refractory manufacturer and processor of refractory minerals based in the Peak District had problems with a 350 ton Toggle Press developing cracks in the bottom press.

They were able to deliver the part to our Derbyshire workshop where it was shot blasted and crack tested. Welding repairs were undertaken using our Lloyds approved fusion welding procedures for cast iron, giving a repair as strong if not stronger than the original material. All welds were then ground to the correct profile to match existing shape, followed by shot blasting and crack testing before a coat of red oxide primer was applied ready for collection by our customer.

Another economical repair!

For any Industrial Repairs, contact us for an initial survey/quotation.

- Initial Survey/Quotation
- Lloyds Welding Procedures
- Full Crack Detection
- Casting of Parts if Required
- 24 Hour Emergency Service
- All Work Guaranteed

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646

Email: info@slinden.co.uk