



Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

LeFort 600 Shear Head



- Initial Survey/Quotation
- Lloyds Welding Procedures
- Full Crack Detection
- Casting of Parts if Required
- 24 Hour Emergency Service
- All Work Guaranteed

We were approached by an international scrap metal exporters when their LeFort 600 Shear Head needed urgent repairs, due to cracks and wear from daily usage.

When it came to our workshop the head was completely stripped down, removing the blades and wear plates, before undertaking repairs by way of our approved fusion welding procedures for cast steel, grinding up all welds to the correct profile to match existing shape, and fully crack tested.

After the welding and inspection process, we machined all faces before the drilling and tapping of missing bolt holes that hold the wear plates.

The Shear Head was then shot blasted followed by painting with a coat of red oxide primer before a final inspection, and collection by the customer.

For any Emergency Industrial Repairs, contact us for an initial survey/quotation.



*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646

Email: info@slinden.co.uk