Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

TCZ Platen Press

We were approached by a Derbyshire packaging firm to carry out in situ metal stitching repairs to a TCZ Platen Press when it was brought to a halt due to a number of cracks opening up on the machine.

The firm, which counts itself among the market leaders in new breed, printed corrugated packaging, requested the press repairs be carried out with some urgency, so as to minimize the amount of time it was out of action.

Our Engineer attended site and undertook repairs by way of our approved Metal Stitching procedures, followed by grinding up to the correct profile, and fully crack testing. After the stitching and inspection process, the repaired areas were primered ready for the press to continue its service, with the minimum of disruption and at a fraction of the cost of a new machine.

Another economical repair!

For any Emergency Industrial Repairs, contact us for an initial survey/quotation.

- Initial Survey/Quotation
- Metal Stitching
- Full Crack Detection
- Casting of Parts if Required
- 24 Hour Emergency Service
- All Work Guaranteed

Breathing new life into damaged Cast iron components

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS Telephone: +44 (0) 1530 274646 Email: info@slinden.co.uk