





# Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs


## TCZ Platen Press



We were approached by a Derbyshire packaging firm to carry out in situ metal stitching repairs to a TCZ Platen Press when it was brought to a halt due to a number of cracks opening up on the machine.




The firm, which counts itself among the market leaders in new breed, printed corrugated packaging, requested the press repairs be carried out with some urgency, so as to minimize the amount of time it was out of action.



Our Engineer attended site and undertook repairs by way of our approved Metal Stitching procedures, followed by grinding up to the correct profile, and fully crack testing. After the stitching and inspection process, the repaired areas were primed ready for the press to continue its service, with the minimum of disruption and at a fraction of the cost of a new machine. *Another economical*

*repair!*



For any Emergency Industrial Repairs, contact us for a free initial survey/quotation.

- Free Survey/Quotation
- Metal Stitching
- Full Crack Detection
- Casting of Parts if Required
- 24 Hour Emergency Service
- All Work Guaranteed

*Breathing new life into  
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646 Fax: +44 (0) 1530 274647 Email: [info@slinden.co.uk](mailto:info@slinden.co.uk)