



# Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

## Rolls-Royce Manifolds

We were contacted by a customer who had accumulated a small collection of Rolls-Royce exhaust manifolds in various states of repair—rusting, cracked in two, and with historical repairs needing correction.

They were brought into our Derbyshire workshop where the manifolds were sand blasted, followed by crack testing and subsequently welded using our Lloyd's approved welding procedures for cast iron. The repairs were then ground to the correct profile and machined back to correct tolerances, followed by final inspection and painted with a coating of VHT black paint, before customer collection.

For any veteran, vintage and classic repairs, please contact us for a survey/quotation.

- Full Pressure Testing
- Full Crack Detection
- Fixed Cost Repairs
- Lloyds Welding Procedure
- Machining Facilities
- 12 Months Guarantee

*Breathing new life into  
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646

Email: [info@slinden.co.uk](mailto:info@slinden.co.uk)