Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

1898 Aveling & Porter

We were contacted by an Aveling & Porter 1898 Steam Road Roller owner when the front forks (which hold the roller in place) suffered a nasty break into two pieces!

He brought the components into our workshop, where we



conducted crack testing to check for any further damage before undertaking welding repairs by way of our Lloyds approved fusion welding procedures for cast iron, giving a repair as strong if not stronger than the original material.

The welds were then ground up to the correct profile to match existing shape,

before final inspection and crack testing. The forks were then sand blasted and given a coating of red oxide primer, before being collected by a very pleased customer!

For any Steam/Loco casting repairs, please give us a call for an initial quotation.

- On Site Inspection
- Lloyds Welding Procedure
- Full Shot Blasting
- Painting As Required
- Full Machining
- 2 Year Guarantee **

Breathing new life into damaged cast iron components

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS Telephone: + 44 (0) 1530 274646 Fax: + 44 (0) 1530 274647 Email: info@slinden.co.uk