



Slinden Services Ltd

Cast Iron Welding and Engineering

DE DEON 1903



A mono block for a De Deon 1903 veteran car was received at our works for inspection to see if we could repair?

As you can see from the photographs this block was basically scrap (!!)- but due to the fact that this is an irreplaceable component we put our engineers to the test and began repairing this item using our approved Fusion Welding Procedure for cast iron material.

A new sleeve was made and combustion chamber cap which was subsequently machined to fit and welded into place. Following a full pressure test and crack detection the block was then fully machined to accept a standard piston.

This was an extensive process but has now given our client a reconditioned block with many years of service, to enable this veteran vehicle to be enjoyed by future generations to come!

For any Veteran and Vintage repairs contact us for a free survey/quotation.

- Full Pressure Testing
- Full Crack Detection
- Fixed Cost Repairs
- Lloyds Welding Procedure
- Machining Facilities
- 12 Months Guarantee

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: 00 44 (0) 1530 274646 Fax: 00 44 (0) 1530 274647 Email: info@slinden.co.uk