



Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

Alfa Romeo SS Block



A Belgian customer brought an Alfa SS 6-cylinder block to our Derbyshire workshop for repair. It was in a bad way, with many cracks, holes, and old weld which needed removing and replacing.



During the inspection process we cut out the side to check the liners, only to find we would have to make 6 new liners and weld them in to position, along with the other welding repairs, by way of our Lloyds approved fusion welding procedures for cast iron. All weld repairs were then ground to the correct profile to the required specifications, before bead blasting, MPI crack testing, and pressure testing.



A coating of red oxide primer was applied, and a final inspection was carried out, before collection by the customer who will carry out the full machining back at headquarters.



For any veteran, vintage and classic repairs, please contact us for a survey/quotation.



- Full Pressure Testing
- Full Crack Detection
- Fixed Cost Repairs
- Lloyds Welding Procedures
- Machining Facilities
- 12 Months Guarantee

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646

Email: info@slinden.co.uk