




Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

Industrial Gearbox Cover



When a Yorkshire engineering company contacted us requesting our help with urgent repairs to a 50” crack to the gearbox cover from an industrial machine—with the minimum amount of time out of action—we were ready for the challenge!

The gearbox cover was brought to our workshop where our engineers undertook emergency repairs to the crack using our approved metal stitching procedures, followed by grinding up to the correct profile, and fully crack testing. After the stitching and inspection process, the repaired area was primed ready for the refit, enabling the machine to continue its service with the minimum of disruption, and at a fraction of the cost of replacement.

All within a 48 hour turnaround!

For any Emergency Industrial Repairs, contact us for an initial survey/ quotation.

- Initial Survey/Quotation
- Metal Stitching
- Full Crack Detection
- Casting of Parts if Required
- 24 Hour Emergency Service
- All Work Guaranteed

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646

Email: info@slinden.co.uk