



Slinden Services Ltd

Cast Iron Welding and Engineering

Loco Steam Exhaust



A Welsh railway company sent an enquiry regarding a damaged/eroded Loco Steam Exhaust. After initial consultation, we were able to offer our expertise in *both welding and metal stitching*.

This entailed our Engineers to go to site and collect the castings for initial Fusion Welding repairs at our workshops. After these repairs were completed, we were back on site to complete the repairs, by way of cutting and grinding to the repaired castings to ensure a perfect fit.

At this point we applied our Metal Stitching technique to secure the exhausts flanges back to the steam cylinders.

This was a good solid repair and will last for many more years to come.

This repair was extremely economical for our customer as casting of new replacement cylinders would not only be time consuming but also very costly.

For any Steam/Loco casting repairs-please give us a call for a free initial quotation.

- On Site Inspection
- Lloyds Welding Procedure
- Metal Stitching
- Full Shot Blasting
- Painting As Required
- Full Machining
- 2 Year Guarantee **

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: + 44 (0) 1530 274646 Fax: + 44 (0) 1530 274647 Email: info@slinden.co.uk