



Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

Christie Clock Face Frame



We were contacted by a customer needing help with repairs to a historical clock face frame which was broken into many pieces, but required the four main parts repaired via our Lloyds approved fusion welding procedures...

"If you are interested, the clock face is from the Christie Clock tower. This was deemed unsafe by the council who demolished it without consent and are now being forced to rebuild it at vast cost, mostly for the stonework. There is a video of its demolition online which gives a good sense of how comprehensively the entire thing was destroyed!"



The four broken pieces were delivered to our workshop, stripped of any loose parts/hinges and shot blasted. The weld repairs were undertaken by way of our approved procedures for cast iron, ground to the correct profile

before crack testing, then shot blasted, and a black phosphate primer applied. The customer collected the clock face and would then be reinforcing the clock face with a stainless steel band for additional support.

The memorial will now undergo a full reinstatement, using as much of the original stonework as possible, and is expected to be complete by the end of the year.



For any Architectural Restorations, please call us for a survey/ quotation.

- Fixed Cost Quote
- Lloyds Welding Procedures
- Full Crack Detection
 - Full Shot Blasting
 - Painting as Required
 - 2 Year Guarantee



*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646

Email: info@slinden.co.uk