




Slinden Services Ltd

Cast Iron Welding & Metal Stitching Repairs

Yacht Keel Repairs



When we were contacted with a query regarding on site stitching repairs to a cracked cast iron yacht keel, our engineer travelled down to the Cornish boatyard prepared for the “worse-case scenario” until he was able to drill a couple of test sections to







determine the thickness of the material! He was able to repair the 10-inch crack by way of our stitching procedures for cast materials, giving a repair of 80% the original material strength. The repair was then ground up to the correct profile to match existing shape, and fully crack tested.

Both the owner and the yacht engineer were pleased with the results:

“Lovely to meet you in person last week and delighted with the finished results....”

“It looks like a good job, so please pass on my thanks!”

For any Marine repairs, please contact us for a survey/quote.

- 
- 
- 
- 
- 
- 
- Estimates provided
 - Metal stitching
 - Full crack detection
 - Casting of parts if required
 - 24-hr emergency service
 - All work guaranteed

*Breathing new life into
damaged cast iron components*

L3 Olympic House, Westminster Industrial Estate, Measham, Derbyshire, DE12 7DS

Telephone: +44 (0) 1530 274646

Email: info@slinden.co.uk